

Fig. 1




Fig. 2




Fig. 3




Fig. 4




Fig. 5

MS1-1725US
Eugene Luskin
Andrew Petrochuk
David Kizhnerman

602

Vehicle Diagnostics Code Explanation

600

P0530

The problem could be caused by defects in refrigerant compressor. The approximate cost is:

606

610

604

608




Fig. 6

700

